Heritage Stimulus Grants – Church of England

| Name | Project | Grant award | Diocese |
|---------------------------------|--|---------------------------------|--------------|
| Bath Abbey | Installation of heat exchangers; access for maintenance; fire detection system | £458,200 | Bath & Wells |
| Wells Cathedral | North elevation of north transept. Masonry repairs, re-pointing, conservation cleaning. Maintenance work while scaffolding is up. | conservation cleaning. £253,965 | |
| St Peter and St Paul, Aston | Repair of tower steps | £17,947 | Birmingham |
| St Agatha, Sparkbrook | Roof repairs | £17,628 | Birmingham |
| Blackburn Cathedral | External masonry repair and repointing; repair and maintenance of rainwater goods; repairs to glazing | £92,793 | Blackburn |
| Lancaster Priory | Stonework repairs to tower and aisles, structural repair to bellframe and improved access to tower, clock repair | £291,280 | Blackburn |
| Bristol Cathedral | Safety improvements for high-level access | £56,000 | Bristol |
| Yate, St Mary | Roof repairs - north aisle roof, valley between north aisle and nave, Lady Chapel and the valley between the Lady Chapel and the chancel. | £223,477 | Bristol |
| Canterbury Cathedral | Masonry works to west tower | £642,400 | Canterbury |
| Canterbury, St Martin | Installation of lightning conductor | £4,890 | Canterbury |
| Carlisle Cathedral | Replacement of rainwater goods | £27,508 | Carlisle |
| Chester Cathedral | Conservation work to baptistry floor | £16,501 | Chester |
| Chester, St John the Baptist | Roof repairs to north and south aisles, north and south transept and Lady Chapel | £180,496 | Chester |
| Brighton, St Mary Kemp Town | Repair or replacement of rainwater goods and valley gutters; some replacement of roof slates. | £53,000 | Chichester |
| Brighton, St Peter | Repairs to tower masonry | £245,000 | Chichester |

| Chichester Cathedral | Repair of flat roof to space intended for conversion to lavatories | £149,548 | Chichester |
|---|--|--------------------|------------|
| Horsham, St Mary | Repair of roof of the boiler room and reconfigure guttering £9,86 | | Chichester |
| St Leonards on Sea, Christ Church | Refurbishment of the tower and spire | £89,370 Chichester | |
| Coventry Cathedral | Urgent works to prepare cathedral for City of Culture 2021 | £443,373 | Coventry |
| Coventry, Holy Trinity | Stonework repairs mostly on south elevation | £65,350 | Coventry |
| Warwick, St Mary | Improvement of rainwater disposal, roof detailing and surface water drainage | £108,160 | Coventry |
| Chesterfield, St Mary and All Saints | Replacement of roof coverings to chancel and north and south aisles | £281,549 | Derby |
| Derby Cathedral | Fire detection system | £106,570 | Derby |
| Repton, St Wystan | Roof replacements and gutter repairs. South porch, nave and south aisle roof lead repairs. North and south gutter repairs. ` | £19,511 | Derby |
| Ely Cathedral | Repair of lantern leadwork and installation of high-level walkways | £99,296 | Ely |
| Exeter Cathedral | Works to allow progress with larger NLHF- funded project | £201,847 | Exeter |
| Totnes, St Mary | Masonry repairs - tower repairs, south side and porch repairs to the parapets and pinnacles and chancel windows. Boof | | Exeter |
| Gloucester Cathedral | Works to W window of cathedral tower and W windows of N transept | £169,055 | Gloucester |
| Tewkesbury Abbey | Roof repairs in the nave and aisles, repairs to parapet copings, long term environmental monitoring. | £123,120 | Gloucester |
| Ledbury, St Michael and All Angels | Replace failed plastic gutters and downpipes in cast iron | £54,049 | Hereford |
| Leominster Priory | Relay tower lead roof, stonework repairs to parapet and pinnacles, refurb flagpole and weathervane | £91,519 | Hereford |

| Ludlow, St Laurence | Repair to the St Leonard's Arch (entrance to the churchyard) to make it safe. | £24,680 | Hereford |
|---------------------------------|---|--|------------|
| Bradford Cathedral | Floor repairs; Asbestos removal; Fire detection; Roof repairs; Clerestory window repairs; | ection; Roof repairs; Clerestory window £144,409 | |
| Chapel Allerton, St Matthew | Masonry repairs, overhaul of rainwater goods, internal plaster repairs £65,000 | | Leeds |
| Halifax Minster | Roof repairs, stonework repairs and £124,204 | | Leeds |
| Leeds Minster | Relay lead roofs to tower, Lady Chapel, City of Leeds room and vestries | £326,237 | Leeds |
| Ripon Cathedral | South Range conservation works. Re- roofing, masonry repairs, rainwater goods, window and tracery repairs, works to enable PV panels, shelter coating, repair of roof doorways. | £240,000 | Leeds |
| Leicester St Margaret | Repairs to tower stonework and renewal of tower roof covering | £282,520 | Leicester |
| Stafford, St Mary | Replacement boiler, removing high level vegetation and re-pointing | £27,000 | Lichfield |
| Barton-upon- Humber, St Mary | Roof repair following lead theft | £27,656 | Lincoln |
| Grimsby Minster | High level stonework repairs, north aisle gutters and replacement of defunct boiler (Phase 2 of conservation programme) | nd replacement of defunct boiler £81,860 | |
| Holbeach, All Saints | Replacement of belfry louvres, tower stonework repairs | £67,387 | Lincoln |
| Tattershall, Holy Trinity | Application 1. Drainage system replacement - new soakaways | £88,000 | Lincoln |
| , Liverpool Cathedral | Remaining urgent quinquennial works (NB | | Liverpool |
| Limehouse St Anne | Permanent roof and tower access £27,843 | | London |
| St Paul's Cathedral | Paul's Cathedral Roof repairs | | London |
| Manchester Cathedral | Replace lead roof to quire and repoint top of stair turrets | £260,480 | Manchester |

| Hexham Abbey | Repairs to chancel, north transept, nave and nave north aisle roofs | £356,861 | Newcastle |
|--|--|----------|-----------------------------|
| Norwich Cathedral | Works to electrical system (surge protection) | £20,000 | Norwich |
| Abingdon, St Helen | Plaster repairs to north aisle and nave ceiling; other plaster repairs and removal of redundant 1960s heating duct | £20,000 | Oxford |
| Aylesbury, St Mary | High level stonework repairs and repairs to window glass and rainwater goods. | £221,816 | Oxford |
| Peterborough, St John the Baptist | Two applications. 1. Repair to externalwalls, stonework, rainwater disposals and£12,140windows. | | Peterborough |
| Portsmouth Cathedral | Roofing works | £125,477 | Portsmouth |
| Northfleet, St Botolph | Chancel roof repairs, Chancel and south aisle buttress masonry repairs, pointing and pinning. | £97,928 | Rochester |
| Orpington, All Saints | New Damp Proof Course to the south aisle, north aisle, re-pointing, window repairs. | £56,920 | Rochester |
| Milton Abbey | New water and electrical supply to remedy intermittent heating system and inadequate cabling. | £10,000 | Salisbury |
| Salisbury Cathedral | Presbytery Gable conservation - masonry replacements, removing cementitious pointing and ferrous cramps or dowels. | £250,000 | Salisbury |
| Croydon Minster | Repairs to high level stonework and roofs and overhaul of rainwater goods | £212,328 | Southwark |
| London, Kennington St John the Divine | Roof repairs | £16,717 | Southwark |
| Southwark Cathedral | edral Urgent repairs to heating system, N transept floor, and medieval masonry in £93,850 nave | | Southwark |
| Nottingham, St Mary | Roof repairs to St Mary's Tower to include new permanent walkways and handrail. | £70,931 | Southwell & Nottingham |
| lpswich, St Mary le Tower | Internal plaster repairs and replacement of external stone crosses | £33,753 | St Edmundsbury & Ipswich |
| Truro Cathedral | Chapter House steps - new handrails and step nosings | £49,685 | Truro |
| Christchurch Priory | Repairs to stonework, glass and rainwater goods of Lady Chapel; miscellaneous repairs to porch, south nave aisle and south transept (Phase 5b of Conservation Programme. | £230,000 | Winchester |
| Worcester Cathedral | Library roof repairs, new rainwater goods, masonry repairs. Internal improvements to environmental conditions, escape route, maintenance access and facilities. | £241,624 | Worcester |

| Beverley Minster | Replacement of lead roof and gutters to east end of nave (Phase 1 of Nave roof repair) | £600,724 | York |
|------------------------|--|------------|------|
| Beverley St Mary | Repair of stonework and glazing to south nave clerestory (Phase 2 of conservation programme) | £139,280 | York |
| Patrington, St Patrick | Lead roof repairs, re-pointing parapets, repair loose pinnacles. South transept stonework conservation and repair. | £272,000 | York |
| TOTAL GRANTS AWADED | | £9,978,790 | |

Breakdown of grant statistics

- 116 applications received of which 5 were ineligible
- 68 grants awarded, with an overall success rate (excluding ineligible applications) of 61%

| Heritage Stimulus Fund | Amount of funding | % of funding | Number of projects |
|---|----------------------|--------------|-----------------------|
| Total funding | £10,000,000 | 100% | 68 |
| Total to the Province of York (contains 25% of church buildings) | £3,242,843 | 32% | 17 |
| Total to the Province of Canterbury (contains 75% of church buildings) | £6,735,947 | 68% | 51 |
| Total to 10% most deprived areas nationally | £2,050,367 | 21% | 17 |
| Total to 10% least deprived areas nationally | £874,200 | 4% | 3 |
| Total to cathedrals | £4,038,240 | 40% | 23 |
| Total to major churches | £5,940,550 | 60% | 45 |