

This case study focusses on the experience of **St Egelwin the Martyr** church (Diocese of Leicester) updating their heating. Initially they suffered a major set back when an electric under-floor heating project failed as a result of the poor judgments made by a contracted architect. When approaching the problem for a second time, they chose air source heat pumps, with four large but unobtrusive blower units installed in the aisles and directed towards the nave.

The new system is very reliable, making it simple and cheap to run. Under-pew heaters are also used to provide supplementary heat on the



Read the Case Study below.

- [Scalford Case Study | The Church of England](#)

Learn more about Scalford: St Egelwin the Martyr

#### Church Heritage Record

[Scalford: St Egelwin the Martyr - CHR Church \(churchofengland.org\)](#)

#### A Church Near You

[Scalford: St Egelwin - A Church Near You](#)

#### Leicester Diocese Environment Page

[Diocese of Leicester | Environmental Resources \(anglican.org\)](#)

# Also of interest

## Net-zero Carbon Church

[Find helpful guidance](#)

## Net-zero Webinars

[Learn more about Net-zero](#)

## More Case Studies

[Back to the main case studies page](#)

## Eco Church

[Find out more about the Eco Church scheme, run by A Rocha](#)

## Environment Home Page

[Main landing page for environment](#)

## Fundraising

[Information about fundraising options](#)

---

**Source URL:** *<https://www.churchofengland.org/about/environment-and-climate-change/towards-net-zero-carbon-case-studies/large-listed-church>*