

For most of its history, the church of **St John, Upper Norwood** (Diocese of Southwark) has had to contend with subsidence in one form or another, and in recent years it has become a major issue. Along with the neighbouring hall, the church building has suffered serious cracks to the fabric, raising concerns about structural integrity going forwards. Whilst there remains work to be done in securing the site, major steps forward have been made – particularly with the underpinning of the south wall. The church is now in a better position, thanks to a scheme that totalled in the help of some large grant funding.



Read the Case Study below.

- [Upper Norwood Case Study | The Church of England](#)

Learn more about Upper Norwood: St John the Evangelist

Church Heritage Record

[Upper Norwood: St John the Evangelist - CHR Church \(churchofengland.org\)](#)

A Church Near You

[St John the Evangelist, Upper Norwood - A Church Near You](#)

Southwark Diocese Environment Page

[The environment - The Diocese of Southwark \(anglican.org\)](#)

Also of interest

Net-zero Carbon Church

[Find helpful guidance](#)

Net-zero Webinars

[Learn more about Net-zero](#)

More Case Studies

[Back to the main case studies page](#)

Eco Church

[Find out more about the Eco Church scheme, run by A Rocha](#)

Environment Home Page

[Main landing page for environment](#)

Fundraising

[Information about fundraising options](#)

Source URL: <https://www.churchofengland.org/about/environment-and-climate-change/towards-net-zero-carbon-case-studies/protecting-church-subsidence>